

IPC Practice Test Questions and Answers

1. Flux can only be used in the brazing process when:

- A) Brazing copper to brass
- B) Brazing copper to copper
- C) Not allowed
- D) Both A and B

2. What is the likely height of a handicapped toilet?

- A) 13 inches
- B) 15 inches
- C) 18 inches
- D) 22 inches

3. One trap arm may serve a total of how many P-traps?

- A) 3
- B) 1
- C) 2
- D) 4

4. Under the IPC, what is the purpose of a trap primer?

- A) To prevent freezing of trap water
- B) To maintain the water seal in traps subject to evaporation
- C) To increase the trap seal depth beyond 4 inches
- D) To prevent backflow through the trap

Answers: 1-A 2-C 3-B 4-B

For More IPC Questions and Answers FREE, IPC Online Prep Training,
IPC Exam, IPC Study Guide, IPC Flashcards, IPC Quizzes visit:

IPC Practice Test